# IMPLEMENTATION OF QUALITY CONTROL PROCEDURES IN A PLASTO INDUSTRY

by

## **PANTELIS MOISEOS**

### **Project Report Submitted to**

the Department of Mechanical Engineering

of the Higher Technical Institute

Nicosia Cyprus

in partial fulfillment of the requirements

for the diploma of

# TECHNICIAN ENGINEER in MECHANICAL ENGINEERING

June 1995



#### ACKNOWLEDGEMENTS

ŝ

-----

I would like to thank my supervisor, Mr D. Roushas, lecturer and Mr. J. Angeli Lab assistant in Mechanical Engineering at H.T.I. for their assistance and guidance offered me in carrying out the presented diploma project.

I would also like to thank Mr. Petro Chrystodoulides, director of Technoplastics Ltd, and all the people in that company, who helped me by giving me all the necessary informations for the completion of this project.

> Moiseos Pantelis 3rd year student in Mechanical Engineering, H.T.I.

#### ABSTRACT

The object of this project was the implementation of quality control procedures in a plasto industry, which was specified to be the TECH-NOPLASTIC LTD. This factory employ 85 workers and it has a production output of many thousands plastic products.

The whole content of the project is divided into eight main parts, Introduction to Quality Control, Statistical Process Control (SPC), Basic Statistics, Incoming Inspection, Process Inspection, Final Inspection, Economics of Quality and the Plasto Industry

All charts and tables are included in the appendices.

#### CONTENTS

## ACKNOWLEDGEMENTS

CONTENTS

É

ABSTRACT

SUMMARY

INTRODUCTION

#### **CHAPTER 1:**

## **1.0 INTRODUCTION TO QUALITY CONTROL**

- 1.1 Several Definitions of "Quality"
- 1.2. Definitions of "Control"
- 1.3 Meanings of "Quality Control"
- 1.4 Definition of "Quality Control"
- 1.5 The object of Quality Control
- 1.6 Quality History Records.
- 1.7 Organisation for Quality Control Manager
  - 1.7.1. Self Governing Organisation
  - 1.7.2 The Quality Control Manager

#### **CHAPTER 2**

## 2.0 STASTICAL PROCESS CONTROL (SPC)

2.1 Definitions of SPC

2.2 Objective of SPC

2.3 Uses of SPC

2.4 SPC tools/techniques for Quality improvements

2.4.1 Cause and Effect Diagrams

2.4.2 Flow Charts

2.4.3 Pareto charts

2.4.4 Run charts or Trend charts

2.4.5 Histograms

2.4.6 Control charts

2.4.7 Scatter Diagrams

2.4.8 Quality circles

2.5 Gantt charts

2.5.1 Gantt load chart

2.5.2 Gantt schedule chart

2.6 Uses of stastical tools

### CHAPTER 3

## 3.0 BASIC STATISTICS

3.1 Measures of Central Tendency

3.1.1 Arithmetic mean

3.1.2 Mode

3.1.3. Median

3.2 Variability (Measures of Dispersion)

3.2.1 Standard Deviation

3.2.2. Range

#### 3.3 The Normal Distribution

- 3.3.1 The Area Under the Normal Curve
- 3.3.2 Using the Standard Normal Table

### **CHAPTER 4**

### **4.0 INCOMING INSPECTION**

4.1 The role of inspection

4.1.1. How Much and How often to Inspect

4.1.2 When and Where to Inspect

4.1.3 Inspection of Attributes Vs. Variables

4.2 Inspection and Testing for Quality Control

- 4.2.1 Screening or 100% inspection
- 4.2.2 Lot-by-Lot Inspection or sampling

4.3 Assuring Inspection Comformance

4.3.1 Random Sampling

4.3.2 Representativeness

4.3.3 Materials Flow

4.3.4 Awareness

4.4 Acceptance sampling

4.4.1 Acceptance Sampling by Attributes

4.4.2 Acceptance Sampling by Variables

4.4.3 Operating Characteristic (OC) Curves

4.4.4 Constructing an OC curve

4.4.5 Parameters Attending Acceptance Sampling Plans

4.4.6 Quality Indices for Acceptance Sampling

4.4.7 Sampling plans with Fixed Sample SIze/Lot Size

4.4.8 Producer's and Consumer's Risk

- 4.4.9 Sampling Plans
  - 4.4.9.1. Single Sampling
  - 4.4.9.2 Double Sampling
  - 4.4.9.3 Sequential (Multiple) Sampling
  - 4.4.9.4 Selection of the best sampling
- 4.5 Drawing Sampling Plan from the Tables
- 4.6 Defects and Defectives
- 4.7 Normal Inspection
- 4.8 Tightened Inspection
- 4.9 Suitching Rules
- 4.10 Average Outoing Quality, and its Limit
- 4.11 Inspection Records

#### **CHAPTER 5**

## **5.0 PROCESS INSPECTION**

- 5.1 Control Charts
  - 5.1.1. Steps to Follow in Using Control Charts
  - 5.1.2. Control Charts for Variables (X,R) charts
    - 5.1.2.1 Setting X Chart Llmits
    - 5.1.2.2 Setting Range Chart Limits
  - 5.1.3. Control Charts for Attributes
    - 5.1.3.1 p charts
    - 5.1.3.2 np charts
    - 5.1.3.3 c and u control charts
  - 5.1.4 Which chart to use?

5.1.5 Choice of sample size

- 5.1.6 Control limits for Attribute charts
- 5.2 Variability in the Production Process
- 5.3 Process Capability Study

## **CHAPTER 6**

### 6.0 FINAL INSPECTION

6.1 Quality Improvement Campaigns

## CHAPTER 7

## 7.0 ECONOMICS OF QUALITY

7.1 Quality Level and its Cost

7.2 Ratios for Quality Cost Categoreis

7.3 Quality Cost Zones

7.4 Cost Vs. Quality

7.5 Practical Applications for Quality Costs

## CHAPTER 8

## 8.0 A PLASTO INDUSTRY

- 8.1 "Technoplastics Ltd" Plasto Industry
- 8.2 The Departments of a plasto industry
- 8.3 The procedure followed in

producing tubular film.

- 8.4 The procedure followed in bag making
- 8.5 The procedure of different Kinds

of plastic products

8.6 Investigation of the Quality Control

Procedures in incoming inspection

followed in "Technoplastics Ltd" industry

- 8.7 Suggestions for improving existing incoming inspection
- 8.8 Investigation of the existing process inspection in "Technoplastics Ltd" industry
- 8.9 Suggestions for improving existing Process Industry
- 8.11 Final Inspection in "Technoplastics Ltd" plasto industry
- 8.12 Suggestions for improving existing final inspection
- 8.13 General Picture of the defective units causes and their effect
- 8.14 Other suggestions for improving Quality
- 8.15 Economic comparison between the existing and the proposed quality procedures REFERENCES

APPENDICES