

# RESTORATION OF A CHURCH

By:

*Eleni Argyridi*

*Emilio Casteleijn*

**C/646**

Project Report

Submitted to

the Department of Civil Engineering

of the Higher Technical Institute

Nicosia - Cyprus

in partial fulfillment of the requirements

for the award of diploma of

**TECHNICIAN ENGINEER**

in

**CIVIL ENGINEERING**

**JUNE 1993**



## ACKNOWLEDGEMENTS

No diploma project of this kind is possible without the help of a number of persons - and this one is no exception.

We are indebted to our Project Supervisor **Mrs D. Sergides**, not only for her valuable advice, but also for her continuous guidance throughout the project. Our special thanks to **Mr Glavkos Papadouris**, Architect of the Department of Antiquities and our external assessor, for the constructive advice and information he offered us, as well as for his interest and patience.

Many thanks I am obliged to give to **Mr Papageorgiou**, byzantinologist and former head of the department of Antiquities, for his endless knowledge on the subject and to **Pater Eleftherios**, priest of the Ayios Dhometios and Ayios Georghios church, for kindly providing us the historical background.

**Iliana Georghiou** and **Costas Tsangaris** of the staff of the department of Antiquities, not only carried out their responsibilities with care, but their sensitive guidance was most helpful at many points in developing particular themes and concepts.

We are also grateful for the loyal help of **Yioula Kalorkoti** who typed the final manuscript.

For the help of these and many others, we are profoundly obliged.

May 29, 1993

Eleni Argyridi

Emilio Casteleijn

## RESTORATION OF A CHURCH

By:  
**Eleni Argyridi**  
**Emilio Casteleijn**

The aim of this project is to study an old church from the historical, architectural and structural point of view, to investigate the deterioration and finally to propose measures for restoration and conservation of the church.

Measured drawings are included as well as photographs throughout the project for enabling the reader to visualize the present condition of the church as well as it surrounding.

The church selected to be studied is the **Ayios Dhometios church**, an approximately four-hundred-year-old church, situated on the south-east side of Ayios Dhometios, a large suburb of Nicosia, about 2km from the centre of Nicosia.



**Title**

**Acknowledgements**

**Abstract**

**Contents**

<b>CHAPTER 1:</b>	<b>HISTORICAL, SOCIAL AND RELIGIOUS</b>	
	<b>BACKGROUND .....</b>	<b>1</b>
1.1.	Religion .....	2
1.1.1.	General .....	2
1.1.2.	Relationship between Religion and Society .....	3
1.1.3.	Building Temples .....	4
1.2.	History of the Orthodox church .....	7
1.2.1.	Roman Empire .....	7
1.2.2.	Byzantine Empire .....	7
1.2.3.	Frankish Empire .....	9
1.2.4.	Turkish Empire .....	10
1.2.5.	English Empire .....	11
1.2.6.	Independancy .....	11
1.3.	Church under study.....	13
1.3.1.	The Ayios Dhometios District ..	15
1.3.2.	The Ayios Dhometios church.....	21
1.3.3.	Anthestiria '93 .....	29

<b>CHAPTER 2:</b>	<b>ARCHITECTURE.....</b>	<b>31</b>
	2.1. Architecture in General .....	32
	2.2. Types of Byzantine Architecture in Cyprus .....	34
	2.3. Gothic Architecture in General .....	37
	2.4. Architectural character of the church ....	39
	2.5. Architectural details and features .....	42
	2.5.1. The Dome .....	42
	2.5.2. The Belltower .....	44
	2.5.3. The Doorways .....	45
	2.5.4. Windows.....	49
	2.5.5. Special features.....	52
	2.6. Building materials and methods of construction .....	58
	2.7. Churches of the same character as the one under study .....	60
	2.7.1. The cathedral of St John the Theologian.....	60
	2.7.2. Church of Ayia Triada.....	61

<b>CHAPTER 3:</b>	<b>PROPOSED METHODS FOR RESTORATION...</b>	<b>63</b>
	3.1. Restoration (General) .....	63
	3.2. Problems and Remedies .....	64
	3.2.1. General Defects in church.....	64
	3.2.2. Stonework.....	64
	3.2.3. Walls .....	70
	3.2.4. Timber.....	72
	3.2.5. Roof.....	76
	3.2.6. Doors and Windows .....	77
	3.2.7. Floor finishes.....	78
	3.2.8. Painting.....	80
	3.2.9. Alterations and improvements...	82
	3.2.10. Pollution .....	84
	3.2.11. General "Lifting" of the Area....	85
	<b>CONCLUSIONS .....</b>	<b>86</b>
	<b>SELECTED BIBLIOGRAPHY</b>	