# DEVELOPMENT OF A QUALITY CONTROL PROGRAMME IN A SHOE INDUSTRY

by :

Pieris Faklamas

Project report submitted to the Department of Mechanical Engineering of the Higher Technical Institute, Nicosia - Cyprus

in partial fulfillment of the requirements for the Diploma of TECHNICIAN ENGINEER

in

#### MECHANICAL ENGINEERING

June 1990

HIGHER

MSTITUTE

PROJECT NO

1683

#### ABSTRACT

The object of this project was to develop a Quality Control programme in a Shoe Industry.

The whole content of the project is divided into five main parts:

- a) Introduction of Quality Control
- b) An existing programme for making the shoe in a specific industry.
- c) Problems of Quality Control in a Shoe Industry.
- d) Quality Control programme
- e) Analyse individual Quality Control Stations:
  - i) Incoming inspection
  - ii) Process inspection
  - iii) Final inspection

Introduction contains the theory about the Quality Control, an efficient programme of Quality Control and the object of Quality Control.

Then there is a programme for making the shoe from the time the incoming material enters at the factory until the incoming material is converted to the shoe. At the end there is a small programme which is performed in a specific industry for the Quality Control.

On the third part are the problems which arise in a factory for Quality Control.

On the fourth part a sugested programme of Quality Control is described.

The last part contains analytical description for the incoming inspection, the process inspection and the final inspection.

Incoming inspection contains the relevant theory and statistical methods for sampling by Attributes. A suggestion for application is followed combined with all selected tests to be carried out, charts and tables. Also some tests for the incoming material.

Process inspection contains the relevant theory of process inspection with control charts and the control charts for variables. It also contains some tests for the materials.

Final inspection contains the procedure of how to inspect the final products before leaving the factory and to construct the Pareto diagram, which gives an indication of the most frequent errors on the product.

## <u>Contents</u>

	P
Acknowledgements	
Contents	
Abstract	
Chapter I	
Introduction	1
Chapter II	
An existing programme for making the shoe	
in a specific industry	4
Chapter III	
Problems of Quality Control in a shoe	
industry	11
Chapter IV	
4 a) Incoming inspection	
4.1.1) Introduction	15
4.1.2) Process of incoming inspection	15
4.1.3) Inspection and Testing for Quality	Control 16
i) Screening	
ii) Lot by lot inspection	
4.2.1) The Operating characteristic (oc)	Curve 17
4.2.2) Constructing the oc curve	
4.3.1) Types of sampling schemes	20
4.3.2) Sampling by Attributes	21
4.3.3) Inspection of soles	
4.3.4) Inspection of leather	23
4 b) Process Inspection	
4.1.1) Process inspection with Control ch	arts 26
4.1.2) Purpose of Control charts	26
4.1.3) Control charts for variables	26
4.1.4) Example on X-R chart	29
4.2.1) Inspection of soles	33
4.2.2) Inspection of leathers	

PAGE

### PAGE

4.2.3)	Inspection of the other parameters
4 c)	Final Inspection 35
4.1.1)	Setting up final inspection
	Pareto diagram
	Example on Pareto diagram 37
Chapter	V
	ons
001102002	5
Annondia	Ces
Defense	e de la constante de la constan La constante de la constante de Cestante de la constante de la c
Referenc	