ANALYSIS OF FAULT INCIDENTS IN THE TRANSMISSION AND DISTRIBUTION SYSTEM OF EAC

BY: Nicoletta Zalisti

project Report
Submitted to
the Department of Electrical Engineering
of the Higher Tecnical Institude
Nicosia-Cyprus

Project Supervisor: Mr. Ch. Chrysafiades Senior Lecturer

HTI

External Assessor : Dr.Ven. Efthymiou El. Engineer

EAC

June 1997



Analysis of fault incidents of the distribution and transmission of A.E.C.

SUMMARY

The scope of this project is to follow a method of analysis based on a computer software in order to identify the causes of faults that occur, on Distribution system (low voltage, 11kV) and on Transmission system 132&66kV voltage. By doing this we observed that 132 kV system has no unexpected failures such as low system.

The more significant cause for faults is on 11kV system and the cause is lightning stoke which may be direct or indirect, hence, an overvoltage induced on the line cause flashover of the insulation.

The best method of protecting these lines was the installation of surge arresters by following the adopted EAC policy. The improvement on the reliability of the system is shown on specific feeders that surge arresters have already been installed. A complete picture of the positive results of the above policy will be shown in future more clearly for whole EAC network.

CONTENTS

ı	. Acknowledgements	İS
L	. Acknowledgements	,

- II. Summary
- III. Introduction

<u>CHAPTER 1</u> : EAC NETWORK	
1.1 General Background	1
1.2 Build up the network	1
1.2.1 Power stations	3
1.2.2 Moni power station	3
1.2.2 Transmission and Distribution system	4
A. Surge diverter	4
B. Voltage transformer	5
C. Underground cables	5
D. Earthing switch	7
E. Current transformer	7
F. Circuit breakers	8
G. Transformers	10
<u>CHAPTER 2</u> : IDENTIFICATION OF FAULT CAUSES	
2.1 Fault causes	11
2.2 Causes of faults	12
2.3 Computer program for analytical investigation of faults	13
2.3.1 Faults reports on transmission and distribution	13
2.3.2 Faults reports according to the type and manufacture	13
2.3.3 Faults reports on substation and feeder	14
2.3.4 Faults reports according to fault serial number	15
2.3.5 Fault analysis using a computer software for four years:	
-132&66kV system	16
-Conclusions on 132&66kV system	24

-11kVsystem	25
-Conclusions on 11kV system	33
-Low Voltage system	34
-Conclusions on Low Voltage system	42
CHAPTER 3: INSULATION CO-ORDINATION	
3.1 Definition of insulation co-ordination	43
3.2 The insulation co-ordination policy	43
3.3 Insulation co-ordination of 132kV system	45
3.4 Insulation co-ordination of 66kV system	46
3.5 Insulation co-ordination of 11kV system	47
3.6 Protection provided by spark gaps and surge arresters	48
3.7 Summary of insulation co-ordination requirements	49
3.8 Summary and conclusions	51
<u>CHAPTER 4</u> : ANALYSIS OF FAULTS AND THEIR RELIABILITY	ON
<u>CHAPTER 4</u> : ANALYSIS OF FAULTS AND THEIR RELIABILITY THE SYSTEM.	ON
	ON 52
THE SYSTEM. 4.1 Introduction	
THE SYSTEM. 4.1 Introduction	52
THE SYSTEM. 4.1 Introduction	52 54
THE SYSTEM. 4.1 Introduction	52 54 54
THE SYSTEM. 4.1 Introduction	52 54 54 56
THE SYSTEM. 4.1 Introduction	52 54 54 56 57
THE SYSTEM. 4.1 Introduction	52 54 54 56 57
THE SYSTEM. 4.1 Introduction	52 54 54 56 57 57 58
THE SYSTEM. 4.1 Introduction	52 54 54 56 57 57 58 59
THE SYSTEM. 4.1 Introduction	52 54 54 56 57 57 58 59 61
THE SYSTEM. 4.1 Introduction	52 54 54 56 57 57 58 59 61
THE SYSTEM. 4.1 Introduction 4.2 Types of faults that occur on 11kV system 4.3 Effect of lightning on overhead lines 4.4 Conclusions and solutions 4.5 Surge arresters 4.5.1 Operation 4.5.2 Arrester classification 4.5.3 Valve type arresters 4.5.4 Metal Oxide Varistors 4.5.5 The MOV as compared to valve type arresters	52 54 54 56 57 57 58 59 61 62

4.7.2 Protective gaps
4.7.3 Surge arresters
4.8 Analytical results about surge arresters
<u>CHAPTER 5:</u> CONCLUSIONS
€