SAFETY ON SITE

Project Report Submitted by:

MARIOS VASILLIADES

In partial fulfilment of the requirements for the award of the diploma of Technician Engineer in Civil Engineering of the Higher Technical Institute Cyprus.

Project Supervisor: I. ECONOMIDES

Lecture in civil engineering H.T.I.

External Assessor:

Sophos Jason

Type of project:

Individual

Group

Project Number:

C/666

June 1993

2101

SUMMARY

SAFETY ON SITE MARIOS VASSILIADES

The purpose of this project is to investigate the safety on site in Cyprus.

To accomplish this, a number, of appropriate and nonappropriate cases were examined separately. (excavations, cranes, ladders etc) The investigation consisted of the gathering of information relating to the number of accidents occurring over the past few years. (i.e the main cause of accident, the severity of the accident e.t.c.)

Having in mind the above information, examinations were carried out to determine the cause of the accidents in each case separately. Examining each case for faults the following factors were considered:

- (1) condition of site (rain, frost, sun e.t.)
- (2) geometry of site
- (3) environmental area

After completing the investigation and study of the above some possible solutions were suggested to improve or solve the existing situation.

CONTENTS

PAGE

SUMMARY

INTRODUCTION

.

																	•				
CHAPT	TER 1:	REGYLATI	ON A	ND	SZ	\FI	ΞТЗ	ζ :	EN	C	SNC	STI	RUG	CT:	IOI	N N	IOW	RK.	S		
	1.1 S	afety and	hea	ltł	ı	•				•	•	•		٠	•	•	٠	•	٠	٠	1
	1.2 R	egulation	s.	•	•	•	•	•	•	•	•	•	•		•	•	•	•			2
	1.3 S	ite inves	tiga	tic	n	•		•	•			•	•	•							8
	1.3.1	Human Fa	ctor.	s	•	•		•		•	•				•				-		8
																			·	•	Ŭ
СНАРЛ	ER 2:	CONSTRUC	TION	HZ	AZA	RI	DS	II	1 (CYI	PRI	JS									
	2.1 I	ntroducti	on .	•					•	•	•		•		•	•	•		•	1	0
	2.2 C	auses of a	acci	der	nts	;		•	•	•					•	•		•		1	1
	2.2.1	Physical	inj	ury	,		•		•			•	•							1	1
	2.2.2	Scaffold	ing	•			•	•												1	2
	2.2.3	Ladders	•••			•	•		•	•			•						•	1	q
	2.2.4	Machiner	y and	d e	exc	av	rat	ic	ons	5	•						•		•	2	0
	2.2.4	Demolitio	on,	•	•										-		•	•	•	2	ې ۲
	2.3 A	ccidents a	Stat:	ist	ic	s							-				•	•	•	2	Δ
										-	-	-	•	·	•	•	•	•	•		*
СНАРТ	'ER 3:	POSSIBLE	MEA:	SUR	E	WH	IIC	H	CC	JUI	D	BF	E A		רק(ान	ף (n	۵v	л	ח
		ACCIDENT	5				-												A A V	U1	2
	3.1 In	ntroductio	on.				_													ゔ	6
	3.2 Pi	revention	of a		id	en	ts	•	•	•	•	•	•	•	•	•	•	•	•	2	٥ د
	Part 1	I: PHYSIC	AL IN	1.11	IRY				•	•	•	•	•	•	•	•	٠	•	٠	2	0
	3.2.1	Scaffold	ina																	r	c
	3.2.2	Ladders	5	•	•	•	•	•	•	•		•	•	٠	•	٠	•	٠	٠	2	0
	3.2.3	Slopping	root	• fe	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	2	9 1
	3.2.4	Excavatio	1001		•	•	•	•	•	•	•	•	٠	•	•	٠	٠	٠	•	3 2	ן ר
	3 2 5	Demolitic	2015	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	3	3
	3 2 6		of c	•	•	•	•	•	•	•	٠	•	•	٠	•	•	٠	•	٠	3	4
	3 2 7	Safety Pr		JIA	ne	5	•	•	•	•	•	•	•	•	•	•	•	•	٠	3	7
	3 2 8	Openings		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	4	U a
	3 2 0	Upenings	• •	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	4	1
	5.4.5	TIGTINGUS	• •	•	•	•	•	•	•	•	•	•	•	•	•	•	•		•	4	3

Part 2: Risk of ill health

2 2 1	Dharada		۱																		
J. Z. I	Physic	al	na	aza	arc	lS	•	٠	۰		•	٠	٠	۰	۰	٠	•	۰	٠	٠	45
3.2.2	Cold .	•	8	۰	•	•	•			•	•	٠	•	٠	•	٠	٠	٠	•	۰	45
3.2.3	Noice		٠	•	•	٠	•	•	•	•	•	•	٠		•	•	•			•	45
3.2.4	Vibrat	cior	l	٠	٠	•	•	•	•	•	•	•	•	٠	٠	•	8	•	e	۰	45
3.2.5	Lasers	5.	٠	•	•	•	٠	•	•	•	•	•		٠	•	٠	•	•	٠		46
3.2.6	Biolog	gica	al	ha	aza	ard	ls		٠	•	•	•	٠	•	•	•	•	•	•	٠	-46
3.3.2	Additic	nal	L j	lnf	lor	cma	ati	lor	n d	on	sa	afe	etz	7	•	٠	۰	٠	٠	•	47
3.3.1	Inform	nati	lor	ו	•	٠	•	٠	•	•	•	•	•	•	٠	٠	٠	•	•	•	47
3.3.2	Safety	v tı	:ai	lni	.nç	J	•	٠	•	•	•	•	•	•	٠	•		٠	•	•	49
CONCLU	JSIONS	٠	•	•	•	•	•	•	•	•	•	•	•	•	•		•	•	•	•	51
REFERI	ENCES .	•	•	•	•	٠	•		•	•	•	•	•	•		•	•	•	•		53